

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**





FIG. 3




[illegible]

FIG. 5




FIG. 6 is a cross-sectional view of the assembly shown in FIG. 5. It illustrates the central component 10 positioned between two main structural elements, 12 and 14. The central component 10 consists of a base portion 60 and a top surface 72. Internal features include a cavity or channel 92, and several other surfaces labeled 32, 34, 36, 64, 66, and 74. The components 12 and 14 are shown as thick plates with corresponding recessed regions 20 and 52 that accommodate the central component 10.




FIG. 7




FIG. 9




FIG. 8




FIG. 10




FIG. 12




FIG. 13




FIG. 11





FIG. 14






FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22





FIG. 24






FIG. 26




FIG. 27





FIG. 28








FIG. 32

